

Facility Evaluation (Site) Form for: Felipa Sanchez Cruzado |Codigo: 71324

Inspector(s) Name:

Sj-05

Inspection Date:

Tue Oct 24 2017

Inspection Time:

20:00:57 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Felipa Sanchez Cruzado

School Code:

71324

Latitude:

18.28509602

Longitude:

-66.27292329

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **Yes**
- One or More Buildings Flooded: **Yes**
- Other Water Damage in Facility: **No**

Comments:

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **Yes**
- Sewer Service: **No**
- Septic Tank Available: **Yes**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

School has 3 water cistern available but only 2 are available to serve bathrooms. Cafeteria has a cistern but it requires power therefore the cafeteria has no access to water.

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **Yes**

Comments:

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Moderate**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

Overall Areas:

- Recreation Area Damage: **No Data**
- Parking Area Damage: **No Data**
- Falling Hazards in Play Areas: **No Data**
- Standing Water in Play Areas: **No Data**
- Debris or Tree Hazards: **No Data**
- Electrical or Power Line Hazards: **No Data**

Comments:

Lunch Room:

- Cooking Equipment: **No Data**
- Refrigerated or Dry Food Storage: **No Data**
- Operational Exhaust Fan: **No Data**
- Fire Suppression System: **No Data**
- Screens: **No Data**

Comments:

Buildings:

Comments:

Additional Comments:

Findings:

1.No water service. 2.Perimeter fence damage near entrance and water creek. 3.Basketball court: ceiling not safe on top of bleachers.

Recommendations:

1.Fix perimeter fence. 2.Barricade entrance to basketball court clean metal sheet.
