

Facility Evaluation (Site) Form for: Violanta Jimenez |Codigo: 71365

Inspector(s) Name:

SJ-07

Inspection Date:

Mon Oct 23 2017

Inspection Time:

10:08:39 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Violanta Jimenez

School Code:

71365

Latitude:

18.39035223

Longitude:

-66.2475272

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

Comments:

Services:

- Potable Water Service: **No**
- Potable Water Cistern: **No**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Minor/None**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

In the back and side of the school have trees at the floor.

Overall Areas:

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Moderate**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

In the back and side of the school have trees and some cables at the floor.

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **No**
- Fire Suppression System: **No**
- Screens: **Yes**

Comments:

Buildings:

- Building 1: **Green - Inspected**
- Building 2: **Green - Inspected**
- Building 3: **Green - Inspected**
- Building 4: **Green - Inspected**
- Building 5: **Green - Inspected**

- Building 6: **Green - Inspected**
- Building 7: **Green - Inspected**
- Building 8: **Green - Inspected**

Comments:

The school lost the ceiling treatment. The classroom of special education have one window broken.

Additional Comments:

Findings:

1. Debris is in back of the school (already barricaded). 2. Most of the school roof sealant treatment was blown away.

Recommendations:

1. clean debris around the school 2. roof treatment
