

Facility Evaluation (Site) Form for: Nicolas Sevilla |Codigo: 71381

Inspector(s) Name:

SJ-05

Inspection Date:

Tue Oct 31 2017

Inspection Time:

14:24:21 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Nicolas Sevilla

School Code:

71381

Latitude:

18.3913625

Longitude:

-66.24867954

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **Yes**
- One or More Buildings Flooded: **Yes**
- Other Water Damage in Facility: **Yes**

Comments:

Flooding thru mechanical/electrical opening in 1st floor, also thru rooms with balconies in second floor which filters down to second

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **Yes**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **Yes**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Water 1st floor has with low pressure. 2nd and 3rd floor do not have water. Water cistern requires electricity to operate , it appears to be a water rider that requires electricity as well to pump water into the 2nd and 3rd story . Generator is available

but it does not work ; requires a new battery and potential repairs

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

Many air compressors shifted during the storm will have to re-inspect after they revive power. Ventilation- mayortario of the classroom have proper ventilation with the exception of A-201 and A-202 in building A #1

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Minor/None**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

Overall Areas:

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:

Buildings:

- Building 1: **Yellow - Restricted Use**
- Building 2: **Green - Inspected**
- Building 3: **Green - Inspected**

Comments:

Additional Comments:

Water issues is concerning , currently only the first floor receives very low pressure and the school does not have sufficient bathroom in the first floor to serve the school populations

Findings:

Water issues is concerning , currently only the first floor receives very low pressure and the floor does not have sufficient bathroom in the first floor to serve the school populations. mold on first floor one office.

Recommendations:

fix water concern. fix sanitary sewer problem due to no pressures on second floor.
