

# Facility Evaluation (Site) Form for: Luis M. Santiago |Codigo: 71498

---

**Inspector(s) Name:**

Jonas Parker

**Inspection Date:**

Mon Oct 23 2017

**Inspection Time:**

10:26:15 GMT-0500 (Central Daylight Time)

**Type of Facility:**

escuela

**School Name:**

Luis M. Santiago

**School Code:**

71498

**Latitude:**

18.44040465

**Longitude:**

-66.25279037

**Building Contact:****Number of Buildings:**

---

**General:**

- Facility Area Flooded: **Yes**
- One or More Buildings Flooded: **Yes**
- Other Water Damage in Facility: **Yes**

**Comments:**

River flooded the ground floor to 3-6 ft

---

**Services:**

- Potable Water Service: **Yes**
- Potable Water Cistern: **No**
- Sewer Service: **Yes**
- Septic Tank Available: **No Data**
- Electrical Power Service: **No**
- Generator Available: **No Data**
- Gas (LP) Storage Tank Intact: **Yes**

**Comments:**

Water service up to cistern is leaking off the top of the building

---

## **Class Room Ventilation:**

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

### **Comments:**

Small percentage of ac units tipped over.

---

## **Access:**

- Safe Access to Buildings: **Yes**

### **Comments:**

Main gates are damaged

---

## **Perimeter Fences/Walls:**

- Damage to Perimeter or Fence: **Severe**
- Damage to Retaining Wall or Slope: **Severe**

### **Comments:**

Concrete walls and fences tipped over/broken out back

---

## **Overall Areas:**

- Recreation Area Damage: **Severe**
- Parking Area Damage: **Moderate**
- Falling Hazards in Play Areas: **Severe**
- Standing Water in Play Areas: **Moderate**
- Debris or Tree Hazards: **Severe**
- Electrical or Power Line Hazards: **Severe**

### **Comments:**

Electric lines and pole between buildings tipped over and broken with power lines on the ground. Concrete walls tipped over and ready to fall.

---

## **Lunch Room:**

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

### **Comments:**

Need to change the fire extinguishers

---

## **Buildings:**

- Building 1: **Yellow - Restricted Use**
- Building 2: **Yellow - Restricted Use**
- Building 3: **Yellow - Restricted Use**
- Building 4: **Yellow - Restricted Use**
- Building 5: **Yellow - Restricted Use**
- Building 6: **Yellow - Restricted Use**
- Building 7: **Yellow - Restricted Use**
- Building 8: **Yellow - Restricted Use**
- Building 9: **Yellow - Restricted Use**
- Building 10: **Yellow - Restricted Use**

**Comments:**

Mud all over every 1st floor room 1 or 2 inches deep

---

**Additional Comments:**

Thick mud in all ground floor rooms. Debris all around. Hasn't been cleaned up yet.

---

**Findings:**

1. There is a severe problem with sedimentation and it has not been cleaned. 2. There is minor leakage in some classrooms.

---

**Recommendations:**

1. fix the sedimentationproble and cleaned. 2. roof treatment.

---