

Facility Evaluation (Site) Form for: Adolfina Irizarry De Puig |Codigo: 71514

Inspector(s) Name:

Jonas Parker

Inspection Date:

Mon Oct 23 2017

Inspection Time:

08:22:15 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Adolfina Irizarry De Puig

School Code:

71514

Latitude:

18.44096164

Longitude:

-66.25264407

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **Yes**
- One or More Buildings Flooded: **Yes**
- Other Water Damage in Facility: **Yes**

Comments:

River behind the school flooded the grounds and the first floor to about 3-4 feet.

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **No**
- Sewer Service: **Yes**
- Septic Tank Available: **No Data**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Gas tank tipped over

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

5 or so air conditioning units fell

Access:

- Safe Access to Buildings: **Yes**

Comments:

Cistern fell

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Severe**
- Damage to Retaining Wall or Slope: **No Data**

Comments:

Most of the back fence gone

Overall Areas:

- Recreation Area Damage: **Moderate**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Moderate**
- Debris or Tree Hazards: **Moderate**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

Fence down in back and standing water due to river flooding

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:

Gas tank tipped over refrigerators moved outside temporarily to ventilate. Kitchen leaking through the fume hood.

Buildings:

- Building 1: **Green - Inspected**
- Building 2: **Green - Inspected**
- Building 3: **Green - Inspected**

Comments:

Additional Comments:

Lots of damage to the rear fence. Some damage through leaking to office rooms main building. Some leaking in the annex. Leaking through the fume hood in the kitchen. Whole first floor was flooded by river. Community doing great job of cleaning up.

Findings:

1. Moderate leaking in the office area, reception has mold. 2. The school was flooded 4ft because of the river on the back of the school.

Recommendations:

1. roof treatment and clean the mold.
