

Facility Evaluation (Site) Form for: Jose Robles Otero |Codigo: 71522

Inspector(s) Name:

Jonas Parker

Inspection Date:

Mon Oct 23 2017

Inspection Time:

08:04:32 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Jose Robles Otero

School Code:

71522

Latitude:

18.44413461

Longitude:

-66.22944686

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

Comments:

No flooding damage

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **No**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **Unknown**
- Gas (LP) Storage Tank Intact: **No**

Comments:

The school is closed bc no gas and power for exterior light hanging down

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

Louvred windows

Access:

- Safe Access to Buildings: **No**

Comments:

Fallen conductor in front parking area

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Moderate**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

A few damaged areas

Overall Areas:

- Recreation Area Damage: **Moderate**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Moderate**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Moderate**

Comments:

Awning hanging near therapy bldg. Neutral conductor down on ground at front entrance.

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:

Much food stolen, gas tanks stolen, gas piping damaged/ sections missing

Buildings:

- Building 1: **Yellow - Restricted Use**
- Building 2: **Red - Unsafe**
- Building 3: **Yellow - Restricted Use**
- Building 4: **Green - Inspected**

Comments:

Additional Comments:

concrete wall for gas for gas storage about to fall. Awning near the back is a falling hazzard. Electrical conductor fallen in front of the school is a hazzard

Findings:

1. Metal structure collapsed between the walkway of the main building and kindergarten. 2. High voltage wire is grounded in front of the school. 3. There's no access to special needs classroom because of ground movement.

Recommendations:

1. clean metal structure of the main building and kindergarten. 2. clean the wire in front of the school. 3. barricade the area of special need classroom.
