

Facility Evaluation (Site) Form for: Pedro P. Casablanca |Codigo: 73650

Inspector(s) Name:

Agosto, Allwes, McDonald

Inspection Date:

Mon Oct 23 2017

Inspection Time:

08:51:57 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Pedro P. Casablanca

School Code:

73650

Latitude:

18.39475192

Longitude:

-66.12651366

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

Comments:

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **No**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

one ac unit was not working prior to Maria. window ac units missing supports on bldg 1.

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Severe**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

severe damage to most of the fencing from fallen trees.

Overall Areas:

- Recreation Area Damage: **Severe**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Moderate**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Severe**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

lots of downed trees and debris all over play areas and recreation areas.

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **No**
- Fire Suppression System: **No Data**
- Screens: **Yes**

Comments:

refrigeration could not be evaluated with no pwr. exhaust fans not working.

Buildings:

- Building 1: **Green - Inspected**
- Building 2: **Green - Inspected**
- Building 3: **Green - Inspected**

- Building 4: **Green - Inspected**
- Building 5: **Green - Inspected**
- Building 6: **Green - Inspected**
- Building 7: **Yellow - Restricted Use**

Comments:

overall for school is YELLOW. bldg 7 is bleachers on bb court should be restricted due to failure of two concrete sections from tree impact. Minor water infiltration into second floor rooms for all bldgs not a safe issue.

Additional Comments:

4 lights for bb court damaged.

Findings:

1. Severe damage from fallen trees in perimeter fence. 2. Two bleacher sections fell because of a tree impact. 3. small lake nearby previously flooded the school grounds but have been cleaned.

Recommendations:

1. a small lake nearby previously flooded the school grounds but has been cleaned. 2. barricade of bleacher areas until is fixed 3. barricade the perimeter area until is fixed.
