Facility Evaluation (Site) Form for: Su Antonio Rivera Rivera | Codigo: 76257

Inspector(s) Name: SJ-14 **Inspection Date:** Thu Oct 26 2017 **Inspection Time:** 09:50:44 GMT-0500 (Central Daylight Time) **Type of Facility:** escuela **School Name:** Su Antonio Rivera Rivera School Code: 76257 Latitude: 18.27836787 Longitude: -66.1926078 **Building Contact:** Number of Buildings:

General:

- Facility Area Flooded: No
- One or More Buildings Flooded: No
- Other Water Damage in Facility: No

Comments:

Services:

- Potable Water Service: Yes
- Potable Water Cistern: Yes
- Sewer Service: No
- Septic Tank Available: Yes
- Electrical Power Service: No
- Generator Available: No
- Gas (LP) Storage Tank Intact: Yes

Comments:

Class Room Ventilation:

- Adequate Classroom Ventilation: Yes
- AC System Operating: No

Comments:

Access:

• Safe Access to Buildings: Yes

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: Moderate
- Damage to Retaining Wall or Slope: Minor/None

Comments:

Partially collapsed fence at the back and a completely collapsed fence in front of basketball court.

Overall Areas:

- Recreation Area Damage: Moderate
- Parking Area Damage: Minor/None
- Falling Hazards in Play Areas: Minor/None
- Standing Water in Play Areas: Minor/None
- Debris or Tree Hazards: Moderate
- Electrical or Power Line Hazards: Minor/None

Comments:

Some debris around school area.

Lunch Room:

- Cooking Equipment: Yes
- Refrigerated or Dry Food Storage: Yes
- Operational Exhaust Fan: Yes
- Fire Suppression System: Yes
- Screens: No

Comments:

Lunch room only has screens in kitchen area.

Buildings:

Comments:

Additional Comments:

Findings:

1. Partially collapsed fence at the back and a completely collapsed fence in front of basketball court. 2. Some debris around school area. 3. Lunch room only has screens in kitchen area.

Recommendations:

1. Barricade collapsed fence area unit is repaired 2. Barricade debris area until are removed.