# Facility Evaluation (Site) Form for: Papa Juan Xxiii Intermedia | Codigo: 77552

Inspector(s) Name:
Jose Colon,
Inspection Date:
Thu Oct 19 2017
Inspection Time:
08:00:00 GMT-0500 (Central Daylight Time)
Type of Facility:
School Name:
Papa Juan Xxiii Intermedia
School Code:
77552

**Longitude:** -66.17422025

**Latitude:** 18.39452234

**Building Contact:** 

**Number of Buildings:** 

#### **General:**

• Facility Area Flooded: No

• One or More Buildings Flooded: No

• Other Water Damage in Facility: No

**Comments:** 

### **Services:**

Potable Water Service: NoPotable Water Cistern: No

• Sewer Service: Yes

Septic Tank Available: NoElectrical Power Service: No

• Generator Available: No

• Gas (LP) Storage Tank Intact: Yes

**Comments:** 

#### **Class Room Ventilation:**

• Adequate Classroom Ventilation: Yes

AC System Operating: <b>No</b>
Comments:
Access:
Safe Access to Buildings: Yes
Comments:
Perimeter Fences/Walls:
Damage to Perimeter or Fence: Minor/None
Damage to Retaining Wall or Slope: Minor/None
Comments:
Overall Areas:
Recreation Area Damage: Minor/None
Parking Area Damage: Minor/None
Falling Hazards in Play Areas: No Data
Standing Water in Play Areas: Minor/None
Debris or Tree Hazards: Minor/None
Electrical or Power Line Hazards: Minor/None
Comments:
fall hazards left blank on checklist (no comments); rec area: metal structure barricade; parking area: debris trees
Lunch Room:
Cooking Equipment: Yes
Refrigerated or Dry Food Storage: Yes
Operational Exhaust Fan: Yes
Fire Suppression System: Yes
Screens: Yes
Comments:
Buildings:
Comments:
Additional Comments:

# **Findings:**

1. Metal siding damaged 2. Debris hazard in parking area. 3. Recreational area: metal structure

## **Recommendations:**

1. Barricade area where metal siding is damaged until it can be repaired. 2. Barricade debris until they can be removed. 3. Barricade area damaged metal structure is located in the recreational area until it can be repaired.