

# Facility Evaluation (Site) Form for: Alfonso Lopez O'Neill | Codigo: 20065

---

**Inspector(s) Name:**

James Scungio, Alan Fregoso, Ramon Riverra

**Inspection Date:**

Fri Oct 27 2017

**Inspection Time:**

14:37:41 GMT-0500 (Central Daylight Time)

**Type of Facility:**

escuela

**School Name:**

Alfonso Lopez O'Neill

**School Code:**

20065

**Latitude:**

18.28760459

**Longitude:**

-66.07606352

**Building Contact:****Number of Buildings:**

---

**General:**

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

**Comments:**

---

**Services:**

- Potable Water Service: **No**
- Potable Water Cistern: **Yes**
- Sewer Service: **No**
- Septic Tank Available: **Yes**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

**Comments:**

---

**Class Room Ventilation:**

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

**Comments:**

80% of classrooms have AC.

---

**Access:**

- Safe Access to Buildings: **Yes**

**Comments:**

---

**Perimeter Fences/Walls:**

- Damage to Perimeter or Fence: **Moderate**
- Damage to Retaining Wall or Slope: **Minor/None**

**Comments:**

10% of fence bent

---

**Overall Areas:**

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

**Comments:**

---

**Lunch Room:**

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **No**
- Operational Exhaust Fan: **No**
- Fire Suppression System: **No**
- Screens: **Yes**

**Comments:**

No existing exhaust fan or fire suppression system.

---

**Buildings:**

- Building 1: **Green - Inspected**
- Building 2: **Green - Inspected**
- Building 3: **Green - Inspected**
- Building 4: **Green - Inspected**

- Building 5: **Green - Inspected**
- Building 6: **Green - Inspected**
- Building 7: **Green - Inspected**
- Building 8: **Green - Inspected**
- Building 9: **Green - Inspected**

**Comments:**

Building 9 (basketball court) is a community building; the school merely has authorization to use it during the school week, but does not own/cannot modify it.

---

**Additional Comments:**

---

**Findings:**

There is no water service. The school don't have power.

---

**Recommendations:**

No recommendations. Electrician evaluation is recommended.

---