

Facility Evaluation (Site) Form for: S U Pasto | Codigo: 20214

Inspector(s) Name:

Noel Nieves, Ronhny Frias

Inspection Date:

Mon Oct 30 2017

Inspection Time:

08:30:00 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

S U Pasto

School Code:

20214

Latitude:

18.11697433

Longitude:

-66.25466831

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **Yes**
- Other Water Damage in Facility: **No**

Comments:

One building were flooded

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **Yes**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

No electricity facility available

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Minor/None**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

Overall Areas:

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

Internet cables hanging

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:

Buildings:

- Building 1: **Green - Inspected**
- Building 2: **Green - Inspected**
- Building 3: **Green - Inspected**
- Building 4: **Green - Inspected**
- Building 5: **Green - Inspected**

- Building 6: **Green - Inspected**
- Building 7: **Green - Inspected**
- Building 8: **Green - Inspected**
- Building 9: **Green - Inspected**
- Building 10: **Green - Inspected**

Comments:

Building 1= 1 level, class room, Building 2= 1 level, class room, Building 3= 1 level, office administration, Building 4= 1 level, basketball court, Building 5= 1 level, class room, Building 6= 1 level, class room, Building 7= 1 level, class room, Building 8= 2 level, class room, Building 9= 1 level, bath room, Building 10= 1 level, bath room, Building 11= 1 level, class room, Building 12= 1 level, class room,

Additional Comments:

Findings:

Building 12 with filtration thru the metal deck, window damaged in building 8. no power electric

Recommendations:

Repair the metal deck roof in building 12 and replace the damaged window.
