

Facility Evaluation (Site) Form for: El Farallón | Código: 20412

Inspector(s) Name:

SJ-11

Inspection Date:

Thu Oct 26 2017

Inspection Time:

09:19:47 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

El Farallón

School Code:

20412

Latitude:

18.23876203

Longitude:

-66.28918487

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **Yes**

Comments:

Ceiling water filtration.

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **No**
- Sewer Service: **No**
- Septic Tank Available: **Yes**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Communication cables torn down.

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

Access:

- Safe Access to Buildings: **No**

Comments:

Debris blocking exit road.

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Severe**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

All around building perimeter fence is torn down.

Overall Areas:

- Recreation Area Damage: **Moderate**
- Parking Area Damage: **Moderate**
- Falling Hazards in Play Areas: **Moderate**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Severe**
- Electrical or Power Line Hazards: **Severe**

Comments:

Debris (tree and electrical pole) is blocking road exit. Cement plaster blown on one of bldg 1 wall.

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:

Buildings:

- Building 1: **Yellow - Restricted Use**
- Building 2: **Green - Inspected**

- Building 3: **Green - Inspected**
- Building 4: **Red - Unsafe**
- Building 5: **Red - Unsafe**
- Building 6: **Green - Inspected**
- Building 7: **Green - Inspected**

Comments:

Bldg 1 - mold contamination. Severe water filtration, water coming from lamps and crack on ceiling. Bldg 4 - ceiling and wall blown off. Bldg 5 - ceiling and door blown off.

Additional Comments:

Findings:

Bldg 1 - mold contamination. Severe water filtration, water coming from lamps and crack on ceiling. Bldg 4 - ceiling and wall blown off. Bldg 5 - ceiling and door blown off.

Recommendations:

Contact an electricist and a structural engineering recommended to solve issues
