

Facility Evaluation (Site) Form for: Incencio Cintrón Zayas | Código: 20479

Inspector(s) Name:

Marcus Ramos, Heriberto Morales

Inspection Date:

Mon Oct 30 2017

Inspection Time:

08:31:00 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Incencio Cintrón Zayas

School Code:

20479

Latitude:

18.24565225

Longitude:

-66.31103138

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **Yes**

Comments:

Nearby river flooded the facility during the hurricane.

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **Yes**
- Sewer Service: **No**
- Septic Tank Available: **Yes**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **No**

Comments:

Has local water service from community cistern. Gas tanks are temporarily unavailable.

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Severe**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

Rear perimeter fence fully collapsed (missing). Fence behind lunch room partially collapsed.

Overall Areas:

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:

Actually being used as donated fence material storage.

Buildings:

- Building 1: **Green - Inspected**
- Building 2: **Green - Inspected**
- Building 3: **Green - Inspected**

Comments:

barricades are not needed since the whole rear fence is being repaired at the moment by school personal.

Additional Comments:

School personal is repairing the whole rear fencing with donated materials.

Findings:

Nearby river overflowed during the hurricane and flooded the school and its overall muddy. Lunch room is being used for fence materiel storage. Gas tanks where taken to be refilled. Rear perimeter fence is completely missing (school has flowing river to the rear).

Recommendations:

School grounds need to be rid of muddy areas.
