

Facility Evaluation (Site) Form for: Nicolas Aguayo Aldea | Codigo: 20594

Inspector(s) Name:

SJ-09

Inspection Date:

Wed Oct 25 2017

Inspection Time:

12:39:35 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Nicolas Aguayo Aldea

School Code:

20594

Latitude:

18.23243685

Longitude:

-66.03111883

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

Comments:

N/A

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **Yes**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

N/A

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

Some classrooms have A/C units but aren't working because the building don't have electrical power service.

Access:

- Safe Access to Buildings: **Yes**

Comments:

N/A

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Minor/None**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

The basketball perimeter fence and one section of backyard fence is severally damage.

Overall Areas:

- Recreation Area Damage: **Moderate**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Moderate**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

Some communication cables are lay down near building #2 entrance.

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **No**
- Fire Suppression System: **No**
- Screens: **No**

Comments:

N/A

Buildings:

- Building 1: **Green - Inspected**
- Building 2: **Yellow - Restricted Use**

Comments:

N/A

Additional Comments:

Findings:

1-Perimeter fences partially damage 2-Canopy metal roof were destroyed. 3-One classroom don't have acoustic ceiling board. 4-The building has some communication cables near building #2 entrance.

Recommendations:

1-Repair or barricade the fence 2-Barricade that area until canopy is restore or demolished. 3-Contract an communication technician to reinstall or relocate the cables.
