

Facility Evaluation (Site) Form for: Rosa E Molinari |Codigo: 11460

Inspector(s) Name:

MZ-06

Inspection Date:

Mon Oct 30 2017

Inspection Time:

10:15:40 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Rosa E Molinari

School Code:

11460

Latitude:

18.47718504

Longitude:

-66.8189049

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **Yes**

Comments:

Books have damages in some classrooms. No equipment damaged.

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **Yes**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Low voltage power. Two water cisterns, one in cafeteria and one on bathrooms. School director inform that water cisterns over bathrooms was stolen.

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

No power to check A/C units.

Access:

- Safe Access to Buildings: **Yes**

Comments:

No issues.

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Minor/None**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

Three locations where falling trees damaged perimeter fence. One on front of school, one on the south side and other in the back. At this last location no access to school.

Overall Areas:

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

Electric cable hanging from pole in parking but cut from main source.

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:

No issues.

Buildings:

- Building 1: **Green - Inspected**
- Building 2: **Green - Inspected**
- Building 3: **Green - Inspected**
- Building 4: **Green - Inspected**
- Building 5: **Green - Inspected**
- Building 6: **Green - Inspected**
- Building 7: **Green - Inspected**

Comments:

No issues.

Additional Comments:

No issues.

Findings:

One of the water cisterns were stolen. Perimeter fence damaged in three locations due to falling trees. Electric cable hanging from pole in parking but cut from main source.

Recommendations:

Reinstall water cisterns stolen. Barricade broken perimeter fence area until it can be repaired. Electrician evaluation is recommended.
