## **CARTA DE TRAMITE**

Para:	Departamento de Educación Dr. Eligio Hernández Pérez Secretario de Educación							
De:	De: Nombre de la Compañía Consultora: As Associa fes, PSC Dirección Postal: Po Box (184 Conovarias Processor) Teléfono: 707-007-9446 Nombre del Representante Autorizado: Firma:							
Escuela	a: Belon Blanco De ZEqueina	Código:	31/20					
(i	Municipio: Lora Fecha de Inspección: /-/o-2o2o							
Nombre	e del Ingeniero que emite la recomendación: /५५	· Ismael N	muer					
Anejos:								
1.	Recomendación al Secretario							
2.	Estampilla Digital Especial emitida por el CIAPR							
3.	Informe de inspección Ocular							

	i e	a portion of the control of the cont

Α.	GENERAL INFORMATION
1.	Street Address of the School: Calle Carlos Escohar
	City: Loiza State: Pin Zip: 00772
2.	School Name: Esc Belen Blanco de Zegueira
3.	Date of inspection: 10 (enero 120 (4.00 pm)
4.	Date of inspection:  Inspector's Name:  Inspector's
В.	BUILDING SITE INSPECTION
5.	Utility Service Safety:
detecte	TANT–Immediately following an earthquake, check the entire property, especially near appliances, for the smell of gas. If gas odor is d, turn off the gas at the meter where it enters the house. Locate and repair leaks before turning gas back on. If the gas odor persists gas has been shut off, vacate the building and contact the gas utility company immediately.
IMPOR valve, e	TANT–Before entering a damaged, vacant building verify that gas is off. Check the gas meter for damage and position of main gas either a manual valve or a seismically-activated gas shut-off valve. Do not enter the building if gas odor is detected.
	a. Odor of natural gas leakage? YES NO b. Downed powerlines? YES NO
6.	Surrounding topography: (@check one)  Flat  Gently sloping (easily walkable)  Steeply sloping (difficult or impossible to walk in some areas)
7.	Building pad: (®check one)  Flat  Terraced or multilevel  Gently sloping (less than 4-foot ground surface elevation difference across house)  Steeply sloping (greater than 4-foot ground surface elevation difference across house)
8.	Geotechnical Issues: (if yes, provide description and photos)
	a. New cracks in the ground?
	b. Signs of fresh cracking in or movement of hardscape?
	c. Signs of fresh cracking in or movement of retaining walls?
	d. Patterns of cracking that extend through the ground surface, hardscape, and improvements?
	b. Signs of fresh cracking in or movement of hardscape?  c. Signs of fresh cracking in or movement of retaining walls?  d. Patterns of cracking that extend through the ground surface, hardscape, and improvements?  e. Evidence of sand boils or other fresh-appearing deposits of sand or mud?  f. Unusual slumping, rising, or bulging of the ground surface?  g. Evidence of rock falls or slope instability above site?
	f. Unusual slumping, rising, or bulging of the ground surface?
	g. Evidence of rock falls or slope instability above site?
	h. Ground movement or wet areas indicating possible broken underground utility lines?
	i. Other phenomena (e.g., septic tanks surfacing, differential settlement, ground consolidation)?

В.	BUILDING SITE INSPECTION (continued	oi)		YES	NO (
9.	Evidence of earthquake-induced permanent ground def property?	formation i	in the immediate vicinity of the		9
C.	GENERAL BUILDING INFORMATION	1/			
10.	Safety Assessment Tag: (⊡check one)	Gr	een Yellow Red		-
11.	a) Year of original construction (best estimate):			YES	NO
12.	Have any repairs, modifications, or demolition been pe		nce the earthquake?		<u></u>
13.	Building configuration:  a Single story  b. Combination one and two story  c. Full two story  d. Three story  e. Split level  f. Typical  g. Other, describe  Exterior wall finish:	16. 17.	sill bolting:  a. Structure bolted to founda b Structure not bolted to fou c. Don't know  Roof configuration:  a. Gable b Hip c. Flat or very low slope d. Shed		
	a. Stucco b. Panel siding c. Metal siding d. Masonry veneer e. Other, describe	18.	e. Other, describe  Roof cevering:  a. Asphaltic membrane b. Wood shingle or shake		
15.	a. Slab-on-grade b. Crawlspace without cripple walls c. Crawlspace with cripple walls d. Exposed piers or posts e. Typical f. Metal g. Other, describe		c. Concrete d. Metal e. Elastomeric f. Other, describe		

D.		EXTERIOR BUILDING INSPECTION			
	19.	General: (if yes, provide description and photos)  a. Collapse, partial collapse, or building off foundation?  b. Obvious lean in any story?	YES	NO T	N/A
20.		Exterior walls: (if yes, provide description and photos)  a. Fresh cracking at corners of door and window openings?  b. Fresh cracking at building corners?  c. Door or window openings racked out of square?  d. Broken glass in windows or doors?  e. Wall leaning?  f. Bulging or delamination of stucco?  g. Pattern of cracking that extends from the ground surface, through foundation, and wall?  h. Evidence of recent relative movement at mudsill line?  i. At locations where the exterior stucco is continuous from the framing down over the foundation, is there cracking of stucco along the mudsill level accompanied by indications			
		of permanent displacement (sliding) of the building relative to the foundation?  j. Collapse, partial collapse, or separation of masonry veneer?  k. Severe cracking, separations, or offsets at building irregularities?			
21.		Foundation: (if yes, provide description and photos)	ya		
		<ul><li>a. Fresh cracking of exposed perimeter foundation?</li><li>b. Relative movement between slab and footing in "two-pour" slab-on-grade foundations?</li><li>c. Ask homeowner if any earthquake retrofits have been done to the home?</li></ul>			The second secon
		If Y describe:	Parishtoni		THIRD CO.
		<ul><li>d. If the answer to c is Y, were bolts added to connect the home to the foundation?</li><li>e. If the answer to c is Y, were plywood or sheathing added to any cripple walls under the home?</li></ul>			
					1

D.	EXTERIOR BUILDING INSPECTION (continued)			
	22. Kitchen Hook (if yes, provide description and photos)	YES	NO	N/A
	a. Present on external wall?		Ø	
	b. Present at internal location?	NATI TAXABILITY OF	Z	
	c. Collapse or partial collapse?	Annual State of the State of th		
	d. Visible damage or cracking?			
	e. Visible tilting or separation from building?	44000000	ď	
	f. Shifted or loose and displaced		Ø	,,,,,,
	g. Deterioration or deformation	POTENTIAL A		Promotion.
23.	Roof: (if yes, provide description and photos)		Ji.	
	a. Shifted or dislodged or concrete damage?		I	emisozoon
	b. Impact damage to roof from falling object?	erennezze		
	c. Displaced rooftop HVAC units?			
	d. Significantly sagging roof ridgelines?	America.		2254(2) 258(4)
	e. Signs of movement between rafter tails and wall finishes at eaves?	CONTRACTOR OF THE PARTY OF THE		SECTION
	f Buckled/dislodged flashing or tearing of roof membrane, roof/wall intersections in split	and the state of t	E Company	
	level buildings, additions, or other building irregularities?			
	g. Tearing of roof membrane or deck waterproofing at re-entrant corners?			
	h. Toppling, shifting, or damage/leakage at refrigerant and electrical lines of rooftop			
	mechanical equipment?			
	i. Shifting of or damage to solar panels?		ANYE SAME	
				(

D.	EXTERIOR BUILDING INSPECTION (continued)			
24.	Attached or abutting improvements: (if yes, provide description and photos)	YES	NO	N/A
	a. Collapse, partial collapse, or separation of attached porches, carports, Gazebos, or	Ш		Ш
	awnings?	П	W.	
	b. Evidence of recent settlement or displacement of exterior steps, patios,			
	or walkways relative to the building?  c. Signs of movement between building floor and/ or exterior hardscape or retaining			
	wall along the uphill side of hon steeply sloping sites?			
	d. Toppling, shifting, or damage/leakage at refrigerant and electrical lines of		U	
	air conditioning condenser unit(s)?			
25.	Independent exterior improvements: (if yes, provide description and photos)			
	a. Damaged detached gazebo?			
	b. Damage to fences / privacy walls?			
	c. Damage to retaining walls?			
	d. Damage to walkway?			
	e. Evidence of leakage from water supply lines?			
	f. Toppling, shifting, or damage/leakage at fuel connection of propane tanks?			
	g. Others damage			Ш
E.	INTERIOR INSPECTION			
26.	General information			
	If interior access not possible, identify reason	nish		
	i. Red tag ii. Hazardous materials iii. Plaster on gypsum	lath		
	iii. Other hazardous condition, describe iv. Other, describe	A //	ison	
	describe	1100	9	
	iv. Other, describe			

(2003) (2003) (2003)	INTERIOR INSPECTION (continued)			
27.	Walls: (if yes, provide description and photos)	YES	NO	N/A
	a. Fresh cracking, buckling, spalling, or detachment of interior wall finish at corners of			
	door and window openings?		ľ	
	b. Fresh cracking of wall finishes at wall corners or wall/ceiling intersections?		Ø	
	c. Door or window openings racked out of square?		I,	
	d. Wall leaning?			and the same of th
	e. Pattern of cracking that extends from the floor slab through the wall?	CONTROL CONTRO	Ø	
	f. Movement or sliding of walls relative to the floor?		g	
	g. Severe cracking, separations, or offsets at building irregularities?	and a second	Ø,	
	h. Doors damaged, difficult to operate, or inoperable?	Secretaria		
	i. Windows damaged, difficult to operate, or inoperable?	- COUNTRY OF THE PROPERTY OF T	Y	
28.	Ceilings: (if yes, provide description and photos)		<u>/</u> /	The second
	a. Collapse of ceiling finish?	LOCULIUM .	g/	entroposito.
	b. Fresh cracking of ceiling finishes, especially at re-entrant corners; cracks along corner	and Assessed		commission.
	bead at stairwell openings; cracking or tearing of finishes at ceiling/wall juncture; or multiple			
	"nail pops"?		/1	
	c. Damage to ceiling finishes in vicinity of corridors or commons places?	est a data della		
	d. Separations or cracks in ceiling finishes at split-levels, re-entrant corners,	ASSESSED	$\square$	
	additions, appendages, or other building discontinuities?			•
	e. Water damage or evidence of recent leakage from plumbing lines or roofing?	CHACAGO		
				ž
				College

paras paras paras	INTERIOR INSPECTION (continued)			
29.	Floors: (if yes, provide description and photos)	YES	NO	N/A
	a. Evidence of recent sloping, sagging, settlement or displacement of floors?			
	b. In slab-on-grade locations, fresh cracking of floor slab or floor finishes?			
	c. Significant sagging or unusual bounciness of floors frames?	(Williams) or		
	d. Separations or cracks in floor finishes at split-levels, re-entrant corners, additions,	seconda.	ansonal.	
	appendages, or other building discontinuities?		rva (	T-1
	e. Signs of movement between floor and exterior hardscape or retaining wall along	THE COLUMN TO SERVICE OF THE SERVICE OF T		kennuud
	the uphill side of homes on steeply sloping sites?	Normanian N	TCT .	
	f. A pattern of fresh cracks, gaps, or joint separations in floor finishes?			haterioon.
	g. Impact damage to floor finishes from falling contents?		dentident	
			<b></b> 1	
30.	Mechanical systems: (if yes, provide description and photos)	and the second		
	a. Displaced connection of appliance flues connected to chimneys?			one and the second
	b. Toppling, shifting, leakage from tank, leakage from water connections displaced flue	erandos esta esta esta esta esta esta esta est		
	connection or damage/leakage at gas line or electrical connection of water heater?	en e		
	c. Shifting, damage/leakage at gas line, flue connection, electrical connection, refrigerant line,			
	and condensate drain connection of furnace or air conditioning fan-coil unit?			
	d. Damage to gas line of gas stoves or gas fueled clothes dryers?	<del></del>		
	e. Damage to toilets?			
	f. Decreased or restricted water pressure at appliances, faucets, or toilets?			
	g. Toppling or shifting of free-standing wood stove and/or flue?			panosov
	h. Toppling, shifting, damage/leakage at fuel connection of fuel oil tank?			
	i. Other Damage in the dining room	Parameteria.		
	j. Damage near the gas tank			
		Laurenceral	kejaund	ii

2200 2200 2000 2000 2000 2000 2000 200	INTERIOR INSPECTION (continued)			Ŷ.
31.	Architectural woodwork and special finishes: (if yes, provide description and photos)	YES	NO	N/A
	a. Shifting of or damage to kitchen or bathroom cabinetry?	PANTS (III.S. S.	ø,	
	b. Impact damage to countertops from falling objects?	proveninte de la companya del companya de la companya del companya de la companya	四一	enamora d
	c. Cracking of ceramic tile in showers or tub/shower enclosures consistent with	Annabet 25.5	Constitution of the Consti	
	earthquake damage to adjacent wall finishes?			
2000 2000 8	CONTINGENTINSPECTIONS			
l		YES	NO	N/A
32.	Retaining Tank Wall damage?	atti yanaa	Lautzimma	
33.	Mark the second	- Immunia	- DY	
00.	Water tank or other field subterranean structure			V

G.	RECOMENDA	CIÓN AL SECRETARIO		
	Departamento de Dr. Eligio Hernáno Secretario de Edu	dez Pérez		
	Hora de Entrada a Inspección:	4:00 pm	Hora de Salida de Inspección:	5:30pm
	Escuela:	Belen Blanco de Zeguerra	Código:	31120
	Municipio:	9:00 pm Belen Blanco de Zequera Loiza	Fecha de Inspección:	5:30pm 31120 10leneol2020
	Abrir Escuela (Ve	rde)		
	Abrir Parcialmente	e la Escuela (Amarillo)		
	No Abrir la Escue	la (Rojo)		
	Comentarios:	MINGUNO		
	Nombre (Letra de l	n P	224y9 (* #Licencia	LICSello RICO

J. MARRE INGENIERO LICENCIADO



#### COLEGIO DE INGENIEROS Y AGRIMENSORES DE PUERTO RICO

PO Box 363845 \* San Juan, Puerto Rico \* 00936-3845 Tel. 787-758-2250 \* Fax. 787-758-7639

#### **ESTAMPILLA DIGITAL ESPECIAL (EDE)**

Ing. Ismael J. Marrero Rivera, PE





SELLO PROFESIONAL

Práctica de:

Ingeniería

Licencia:

22489

Renglón:

Certificación

Descripción del Trabajo: Inspección y Verificación de Instalaciones

Fecha de Emisión:

2020-01-20

Monto Emitido:

Número de Serie:

6137-7423-5744-9538

Número de Caso:

31120

Proyecto / Unidad:

Código #31120 Esc. Belén Blanco

Rol del Profesional:

Evaluador

#### Certificación:

El profesional certifica con la emisión de la estampilla digital especial del Colegio de Ingenieros y Agrimensores de Puerto Rico el haber cumplido con las disposiciones de la Sección 11 de la Ley 319 del 15 de mayo de 1938, según enmendada.

La colocación del sello profesional constituye la cancelación de la estampilla digital especial



		i s
		The state of the s
		4
		(