

# Hoja de Trámite

### 22 de enero de 2020

Para: Departamento de Educación Dr. Eligio Hernández Pérez Secretario de Educación							
De:	Calle Pro	n Professional ( ogreso # 50 – 9 7.918.5890 / 5	Suite 202, Faja	ardo PR 00738 fo@ingenium.gr	oup		
Nombre	del Repre	esentante Auto	rizado:	Manzu	o Pere-	(	
			Firma:	1	. 17		
Escuela:	Escuela: JULIAN E BLANCO (BALLET) Codigo: 60038						
Municipio	);	SAN JUAN I	Fecha	a Inspeccion:	43	3841	
	Nombre del Ingeniero que emite la recomendación: EFREN RIVERA LIC: 8904						
Documentos Entregados:							
	<ul> <li>Recomendación al Secretario</li> <li>Estampilla Digital Especial emitida por el CIAPR</li> <li>Informe de inspección Ocular</li> </ul>						

Entregado a:		h	Fecha:	1	23	2020	
	ALCOHOL TO THE REAL PROPERTY OF THE PARTY OF	-					

#### GENERAL EARTHQUAKE DAMAGE OCULAR INSPECTION CHECKLIST

A.	GENERAL INFORMATION		
1.	Street Address of the School:		
	City: San Juan State: Puerro Rico Zip:		
2.	School Name: State: Poerto Rico Zip:  School Name: Julian E. Blanco		
3.	Date of inspection:		
4.	Inspector's Name: Efren Rivera		
В.	BUILDING SITE INSPECTION		Va.
5.	Utility Service Safety:		
detecte	TANT–Immediately following an earthquake, check the entire property, especially near appliances, for the si d, turn off the gas at the meter where it enters the house. Locate and repair leaks before turning gas back of gas has been shut off, vacate the building and contact the gas utility company immediately.		
	TANT–Before entering a damaged, vacant building verify that gas is off. Check the gas meter for damage a ither a manual valve or a seismically-activated gas shut-off valve. Do not enter the building if gas odor is de		ain gas
	a. Odor of natural gas leakage?	NO NO	£
6.	Surrounding topography: (@check one)  Flat Gently sloping (easily walkable)  Steeply sloping (difficult or impossible to walk in some areas)		
7.	Building pad: (Echeck one)  Flat  Terraced or multilevel  Gently sloping (less than 4-foot ground surface elevation difference across house)  Steeply sloping (greater than 4-foot ground surface elevation difference across house)	er er	
8.	Geotechnical Issues: (if yes, provide description and photos)	YES	NO
	a. New cracks in the ground?		
m	b. Signs of fresh cracking in or movement of hardscape?		
	c. Signs of fresh cracking in or movement of retaining walls?		
-	d. Patterns of cracking that extend through the ground surface, hardscape, and improvements?		
	e. Evidence of sand boils or other fresh-appearing deposits of sand or mud?		
	f. Unusual slumping, rising, or bulging of the ground surface?		
	g. Evidence of rock falls or slope instability above site?		
	h. Ground movement or wet areas indicating possible broken underground utility lines?		
	i. Other phenomena (e.g., septic tanks surfacing, differential settlement, ground consolidation)?		

# GENERAL EARTHQUAKE DAMAGE OGULAR INSPECTION CHECKLIST

В.	BUILDING SITE INSPECTION (continued)		YES	NO
9.	Evidence of earthquake-induced permanent ground deformation in the immedia property?	ate vicinity of the		
c.	GENERAL BUILDING INFORMATION			
10.	Safety Assessment Tag: (@check one) None Green Ye  (others): Yellow Red	ellow Red		=
11.	a) Year of original construction (best estimate):  b) Total square footage (best estimate):  Have any repairs, modifications, or demolition been performed since the earthough the square forms of the earthough the first performed since the earthough the first performs of the first performed since the earthough the first performs of the first performs of the first performs of the first performance of the f	quake?	YES	NO
13.	Building configuration:  a. Single story  b. Combination one and two story  c. Full two story  d. Three story  e. Split level  f. Typical  g. Other, describe  Exterior wall finish:  16. Sill bolting:  a. Struct  b. Struct  c. Don't  17. Roof configuration:  a. Gabl  b. Hip  c. Flat of  d. Shed	uration: le or very low slope		
	b. Panel siding  c. Metal siding  d. Masonry veneer  a. Asph	naltic membrane d shingle or shake	41	
15.	Foundation configuration:  a. Slab-on-grade  e. Elast			

D.	EXTERIOR BUILDING INSPECTION			1
1:	9. General: (if yes, provide description and photos)	YES	NO	N/A
	a. Collapse, partial collapse, or building off foundation?			
	b. Obvious lean in any story?	AND COMPLETE	回	
20.	Exterior walls: (if yes, provide description and photos)  a. Fresh cracking at corners of door and window openings?  b. Fresh cracking at building corners?  c. Door or window openings racked out of square?  d. Broken glass in windows or doors?  e. Wall leaning?  f. Bulging or delamination of stucco?  g. Pattern of cracking that extends from the ground surface, through foundation, and wall?			
	<ul><li>h. Evidence of recent relative movement at mudsill line?</li><li>i. At locations where the exterior stucco is continuous from the framing down over the foundation, is there cracking of stucco along the mudsill level accompanied by indications</li></ul>			
:	of permanent displacement (sliding) of the building relative to the foundation?  j. Collapse, partial collapse, or separation of masonry veneer?  k. Severe cracking, separations, or offsets at building irregularities?		B'	
21.	Foundation: (if yes, provide description and photos)  a. Fresh cracking of exposed perimeter foundation?  b. Relative movement between slab and footing in "two-pour" slab-on-grade foundations?  c. Ask homeowner if any earthquake retrofits have been done to the home?		<b>D</b>	
	d. If the answer to c is Y, were bolts added to connect the home to the foundation?  e. If the answer to c is Y, were plywood or sheathing added to any cripple walls under the home?		o o	

### GENERAL EARTHQUAKE DAMAGE OCULAR INSPECTION CHECKLIST

D.	EXTERIOR BUILDING INSPECTION (continued)			
	22. Kitchen Hook (if yes, provide description and photos)	YES	NO	N/A
	a. Present on external wall?		Ø	
	b. Present at internal location?			
	c. Collapse or partial collapse?		ď	
	d. Visible damage or cracking?	HUMB		
	e. Visible tilting or separation from building?		Image: second control of the control	
	f. Shifted or loose and displaced		Ø	
	g. Deterioration or deformation			
23.	Roof: (if yes, provide description and photos)		,	
	a. Shifted or distodged or concrete damage?		0	
	b. Impact damage to roof from falling object?		Ø	
	c. Displaced rooftop HVAC units?			
	d. Significantly sagging roof ridgelines?			
	e. Signs of movement between rafter tails and wall finishes at eaves?		Image: second control in the control	
	f Buckled/dislodged flashing or tearing of roof membrane, roof/wall intersections in split			
	level buildings, additions, or other building irregularities?			
	g. Tearing of roof membrane or deck waterproofing at re-entrant corners?			
	h. Toppling, shifting, or damage/leakage at refrigerant and electrical lines of rooftop			
	mechanical equipment?			
	i. Shifting of or damage to solar panels?			Image: Control of the

### GENERAL EARTHQUAKE DAMAGE OCULAR INSPECTION CHECKLIST

D.	EXTERIOR BUILDING INSPECTION (continued)			
24.	Attached or abutting improvements: (if yes, provide description and photos)	YES	NO	N/A
	a. Collapse, partial collapse, or separation of attached porches, carports, Gazebos, or			4
	awnings?			
	b. Evidence of recent settlement or displacement of exterior steps, patios,	Ш		
	or walkways relative to the building?			
	c. Signs of movement between building floor and/ or exterior hardscape or retaining			υΙ
	wall along the uphill side of hon steeply sloping sites?			
	d. Toppling, shifting, or damage/leakage at refrigerant and electrical lines of	Ц		
	air conditioning condenser unit(s)?			
25.	Independent exterior improvements: (if yes, provide description and photos)			
	a. Damaged detached gazebo?			
	b. Damage to fences / privacy walls?	Ц		
	c. Damage to retaining walls?			
	d. Damage to walkway?			
	e. Evidence of leakage from water supply lines?			
	f. Toppling, shifting, or damage/leakage at fuel connection of propane tanks?			
	g. Others damage			Ш
E.	INTERIOR INSPECTION			
26.	General information  a. If interior access not possible, identify reason  b. Typical wall and ceiling	a finish		
	i. Red tag i. Drywall	j inilori		
	ii. Hazardous materials ii. Plaster on gyps			
	iii. Other hazardous condition, iii. Plaster on wood describe iv. Other, describe	delath	plaster	
	describe iv. Other, describe			
	iv. Other, describe			

žu.

200 200 100 B	INTERIOR INSPECTION (continued)			
27.	Walls: (if yes, provide description and photos)	YES	NO	N/A
	a. Fresh cracking, buckling, spalling, or detachment of interior wall finish at corners of			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
	door and window openings?			
	b. Fresh cracking of wall finishes at wall corners or wall/ceiling intersections?			
	c. Door or window openings racked out of square?			
	d. Wall leaning?		团	
	e. Pattern of cracking that extends from the floor slab through the wall?			
	f. Movement or sliding of walls relative to the floor?			
	g. Severe cracking, separations, or offsets at building irregularities?			
	h. Doors damaged, difficult to operate, or inoperable?			
	i. Windows damaged, difficult to operate, or inoperable?			
28.	Ceilings: (if yes, provide description and photos)			
	a. Collapse of ceiling finish?			
	b. Fresh cracking of ceiling finishes, especially at re-entrant corners; cracks along corner		0	
	bead at stairwell openings; cracking or tearing of finishes at ceiling/wall juncture; or multiple	!		
	"nall pops"?			
	c. Damage to ceiling finishes in vicinity of corridors or commons places?			
	d. Separations or cracks in ceiling finishes at split-levels, re-entrant corners,			
	additions, appendages, or other building discontinuities?		<i></i>	
	e. Water damage or evidence of recent leakage from plumbing lines or roofing?			

GINEA GINEA GIZZZZ B	INTERIOR INSPECTION (continued)			
29.	Floors: (if yes, provide description and photos)	YES	NO	N/A
	a. Evidence of recent sloping, sagging, settlement or displacement of floors?			
	b. In slab-on-grade locations, fresh cracking of floor slab or floor finishes?	,		
	c. Significant sagging or unusual bounciness of floors frames?	<b>L</b>		
	d. Separations or cracks in floor finishes at split-levels, re-entrant corners, additions,			
	appendages, or other building discontinuities?	r <del>-1</del>		
	e. Signs of movement between floor and exterior hardscape or retaining wall along	were resident to the second	Ľ	LJ
	the uphill side of homes on steeply sloping sites?			m
	f. A pattern of fresh cracks, gaps, or joint separations in floor finishes?			المسبا
	g. Impact damage to floor finishes from falling contents?	Accounts.	LJ	LJ
30.	Mechanical systems: (if yes, provide description and photos)			ll
	a. Displaced connection of appliance flues connected to chimneys?	П		
	b. Toppling, shifting, leakage from tank, leakage from water connections displaced flue	bramansk	لستا	bonood
	connection or damage/leakage at gas line or electrical connection of water heater?		<b>173</b>	<del></del> 1
	c. Shifting, damage/leakage at gas line, flue connection, electrical connection, refrigerant line,			[] []
	and condensate drain connection of furnace or air conditioning fan-coil unit?	Comments.	in comment	<u>                                     </u>
	d. Damage to gas line of gas stoves or gas fueled clothes dryers?	<b>[</b> -7]		П
	e. Damage to toilets?	Loui	L-1	<u>                                     </u>
	f. Decreased or restricted water pressure at appliances, faucets, or toilets?			П
	g. Toppling or shifting of free-standing wood stove and/or flue?			
	h. Toppling, shifting, damage/leakage at fuel connection of fuel oil tank?			
	i. Other Damage in the dining room			
	j. Damage near the gas tank			
				,

	INTERIOR INSPECTION (continued)			
31.	Architectural woodwork and special finishes: (if yes, provide description and photos)	YES	NO	N/A
	a. Shifting of or damage to kitchen or bathroom cabinetry?			
	b. Impact damage to countertops from falling objects?			
	c. Cracking of ceramic tile in showers or tub/shower enclosures consistent with	- MARIENA A		
	earthquake damage to adjacent wall finishes?			
			Held till History (bestyrens myskere fred bleverklebenske krief	apenda ministracional est s Cannos (F)
F.	CONTINGENTINSPECTIONS			
		YES	NO	N/A
32.	Retaining Tank Wall damage?			
33.	Water tank or other field subterranean structure			

G.	RECOMENDACIÓN AL SECRETARIO	
	Departamento de Educación Dr. Eligio Hernández Pérez Secretario de Educación	
	a Inspección: $8-30$ Escuela: $Tulian \in Blanco$	Hora de Salida de Inspección: 10:30  Código: 60038  Fecha de Inspección: 11 Énero 2020
	Abrir Escuela (Verde)  Abrir Parcialmente la Escuela (Amarillo)  No Abrir la Escuela (Rojo)	
	Comentarios: Luego de real ocular de la escuele de San Juan mis ca siquientes; l- No se ident	omentarios son los
		INGENIERO CARALLINGENIERO
	Efren Rivera Carraguillo Nombre (Letra de Molde)  Al Managaille #	INCEMIERO LICENCIADO L





()







#### COLEGIO DE INGENIEROS Y AGRIMENSORES DE PUERTO RICO

PO Box 363845 \* San Juan, Puerto Rico \* 00936-3845 Tel. 787-758-2250 \* Fax. 787-758-7639

#### **ESTAMPILLA DIGITAL ESPECIAL (EDE)**

Ing. William Melendez Rivas, PE



Práctica de:

Ingeniería

Licencia:

16383

Renglón:

Certificación

Descripción del Trabajo: Trámites ante Entes Gubernamentales

Fecha de Emisión:

2020-01-21

Monto Emitido:

\$5

Número de Serie:

5967-7753-2160-5985

Número de Caso:

Código Escuela:60038

Proyecto / Unidad:

Escuela Julián E. Blanco, San Juan

Rol del Profesional:

Consultor



#### Certificación:

El profesional certifica con la emisión de la estampilla digital especial del Colegio de Ingenieros y Agrimensores de Puerto Rico el haber cumplido con las disposiciones de la Sección 11 de la Ley 319 del 15 de mayo de 1938, según enmendada.

La colocación del sello profesional constituye la cancelación de la estampilla digital especial