

Facility Evaluation (Site) Form for: Felix Cordova Davila |Codigo: 12070

Inspector(s) Name:

Lebron, Castro & Gimenez

Inspection Date:

Mon Oct 23 2017

Inspection Time:

12:20:56 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Felix Cordova Davila

School Code:

12070

Latitude:

18.43553526

Longitude:

-66.4836298

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

Comments:

Services:

- Potable Water Service: **No**
- Potable Water Cistern: **No**
- Sewer Service: **No**
- Septic Tank Available: **Yes**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Neighboring community has water from AAA. AAA has a facility beside the school. It needs to be investigated why school steel has no water.

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Minor/None**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

Minor damage to perimeter fence will be repair by BASF contractors.

Overall Areas:

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **No**
- Operational Exhaust Fan: **No**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:

Buildings:

Comments:

Additional Comments:

Findings:

1. Humidity and mold problems in bathroom of main building 2. Fallen Tree at the access area (debris) 3. Falling data cables lines in the building #3

Recommendations:

1. Remove all mold and provide controls for humidity 2. Barricade the area at the fallen tree 3. Put in place the data cables
^Note: the school is adopted by a private company, they indicated that they will do all necessary repairs
