

Facility Evaluation (Site) Form for: Teresa Prestamo |Codigo: 71126

Inspector(s) Name:

SJ-07

Inspection Date:

Mon Oct 23 2017

Inspection Time:

08:09:03 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Teresa Prestamo

School Code:

71126

Latitude:

18.40421563

Longitude:

-66.27264751

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **Yes**
- One or More Buildings Flooded: **Yes**
- Other Water Damage in Facility: **No**

Comments:

The entrance of the school was flooded.

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **No**
- Sewer Service: **No**
- Septic Tank Available: **Yes**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

The cistern is broken. From hurricane Irma the school don't have water service.

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Minor/None**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

Overall Areas:

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Moderate**

Comments:

Behind buildings 3 and 4 have a electrical high tension line.

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **No**
- Fire Suppression System: **No**
- Screens: **Yes**

Comments:

The food was seized because of rats.

Buildings:

- Building 1: **Green - Inspected**
- Building 2: **Green - Inspected**
- Building 3: **Green - Inspected**

- Building 4: **Yellow - Restricted Use**

Comments:

Building 1: lunch room and classrooms; Building 2: classrooms; Building 3: office; Building 3: classroom. Building 3 was flooded and the roof finishes was rip off. Building 4: offices.

Additional Comments:

Findings:

1. Fallen power lines next to kindergarden building. 2. Rats in food storage area. 3. Water in kindergarden building.

Recommendations:

1. Barricade area and remove fallen power lines. 2. Fumigate food storage area. 3. Evaluate drainage in kindergarden building.
