Facility Evaluation (Site) Form for: Ladislao Martinez | Codigo: 71779

Inspector(s) Name: SJ-08 **Inspection Date:** Mon Oct 23 2017 **Inspection Time:** 09:40:43 GMT-0500 (Central Daylight Time) **Type of Facility:** escuela **School Name:** Ladislao Martinez **School Code:** 71779 Latitude: 18.40964683 Longitude: -66.32459814 **Building Contact: Number of Buildings:**

General:

- Facility Area Flooded: Yes
- One or More Buildings Flooded: No
- Other Water Damage in Facility: No

Comments:

Only basketball court flooded

Services:

Potable Water Service: YesPotable Water Cistern: Yes

• Sewer Service: **Yes**

Septic Tank Available: NoElectrical Power Service: No

• Generator Available: No

• Gas (LP) Storage Tank Intact: Yes

Comments:

None

Class Room Ventilation:

- Adequate Classroom Ventilation: Yes
- AC System Operating: No

Comments:

Only one office is not adequate ventilated. Therapy office bldg 1D

Access:

Safe Access to Buildings: Yes

Comments:

No safe access to basketball court.

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: Minor/None
- Damage to Retaining Wall or Slope: Minor/None

Comments:

None

Overall Areas:

- Recreation Area Damage: Minor/None
- Parking Area Damage: Minor/None
- Falling Hazards in Play Areas: Minor/None
- Standing Water in Play Areas: Minor/None
- Debris or Tree Hazards: Minor/None
- Electrical or Power Line Hazards: Minor/None

Comments:

None

Lunch Room:

- Cooking Equipment: Yes
- Refrigerated or Dry Food Storage: Yes
- Operational Exhaust Fan: Yes
- Fire Suppression System: No
- Screens: Yes

Comments:

None

Buildings:

- Building 1: Green Inspected
- Building 2: Green Inspected
- Building 3: Yellow Restricted Use
- Building 4: Green Inspected

Comments:

Basketball court because of damages recomended to be restricted.

Additional Comments:

Basketball was flooded, needs clean up and metal roof repairing.

Findings:

1. Lunchroom exhaust fan without top cover 2. Bldg #2: standing water on roof, poor ventilation in classrooms 3. Bldg #4: Rat infested and has debris in playground 4. Basketball court: flooded and metal roof is damaged

Recommendations:

1. Bldg #2: unclog drains and remove standing water 2. Bldg #4: barricade debris in playground until they are removed. Hire exterminator service to deal with rats. 3. Basketball court: restrict access until flooding is cleaned and debris are removed.