

Facility Evaluation (Site) Form for: Centro De Adiestramiento | Codigo: 73494

Inspector(s) Name:

Group 10, Ronhny Frias, Ethel Rivera, Angel Rodriguez

Inspection Date:

Mon Oct 23 2017

Inspection Time:

09:15:05 GMT-0500 (Central Daylight Time)

Type of Facility:

escuela

School Name:

Centro De Adiestramiento

School Code:

73494

Latitude:

18.43434421

Longitude:

-66.40580423

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **Yes**
- One or More Buildings Flooded: **Yes**
- Other Water Damage in Facility: **Yes**

Comments:

Liking in all buildings

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **Yes**
- Sewer Service: **No**
- Septic Tank Available: **Yes**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Class Room Ventilation:

- Adequate Classroom Ventilation: **No**
- AC System Operating: **No**

Comments:

Shops Class rooms without windows

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Minor/None**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

One gate broken at the parking lot entrance

Overall Areas:

- Recreation Area Damage: **Moderate**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

Debris and a tilted trailer used for therapy. Lights fixture almost falling in the basketball court

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:

Buildings:

- Building 1: **Green - Inspected**
- Building 2: **Green - Inspected**

Comments:

Building 1 = shops rooms, office, lunch, class rooms Building 2 = class rooms

Additional Comments:

Findings:

1. The gate at the entrance near the parking lot is damaged. 2. It has hazards in the recreational area due to debris. This area has trailers tilted. no electrical service. 3. There are "RATS PROBLEMS". 4. There are two damaged electronic black boards..

Recommendations:

1. Water service need (special students population with special needs). 2. A/C service because of poor ventilation. 3. Eliminate the leakage problem. 4. Eliminate hanging light fixture from basketball court structure.
