

# Facility Evaluation (Site) Form for: Francisco Rivera Claudio |Codigo: 12245

---

**Inspector(s) Name:**

Sebastian Morales, , ,

**Inspection Date:**

Thu Oct 19 2017

**Inspection Time:**

05:20:00 GMT-0500 (Central Daylight Time)

**Type of Facility:****School Name:**

Francisco Rivera Claudio

**School Code:**

12245

**Latitude:**

18.32597697

**Longitude:**

-66.40150689

**Building Contact:****Number of Buildings:**

---

**General:**

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **Yes**
- Other Water Damage in Facility: **No**

**Comments:**

Buildings were flooded due to water at the roof

---

**Services:**

- Potable Water Service: **No**
- Potable Water Cistern: **No**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

**Comments:**

---

**Class Room Ventilation:**

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

**Comments:**

---

**Access:**

- Safe Access to Buildings: **Yes**

**Comments:**

Needs barricades at school entrance

---

**Perimeter Fences/Walls:**

- Damage to Perimeter or Fence: **Moderate**
- Damage to Retaining Wall or Slope: **Moderate**

**Comments:**

---

**Overall Areas:**

- Recreation Area Damage: **Moderate**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

**Comments:**

Trees at recreational area.

---

**Lunch Room:**

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **No Data**
- Screens: **No Data**

**Comments:**

---

**Buildings:**

- Building 1: **Green - Inspected**

**Comments:**

---

## **Additional Comments:**

---

## **Findings:**

1. Roof treatment highly affected. 2. Trees at the floor of the Recreational area. 3. Buildings were flooded due to water at the roof. 4. Modetared damages to the perimeter fence.

---

## **Recommendations:**

1. Repair the affected roof. 2. Pick-up the trees that are on the floor of the recreational area. 3. Barricade school entrance and perimeter fence until are reaired

---