Facility Evaluation (Site) Form for: Rafael Cordero | Codigo: 70763

| Inspector(s) Name: |
|---|
| Raiza Rivera |
| Inspection Date: |
| Mon Oct 30 2017 |
| Inspection Time: |
| 13:45:00 GMT-0500 (Central Daylight Time) |
| Type of Facility: |
| escuela |
| School Name: |
| Rafael Cordero |
| School Code: |
| 70763 |
| Latitude: |
| 18.43701529 |
| Longitude: |
| -66.12506378 |
| Building Contact: |
| Number of Buildings: |
| General: |
| Facility Area Flooded: No |
| One or More Buildings Flooded: No |
| Other Water Damage in Facility: No |
| Comments: |

Services:

Potable Water Service: YesPotable Water Cistern: No

• Sewer Service: **Yes**

Septic Tank Available: NoElectrical Power Service: No

• Generator Available: No

• Gas (LP) Storage Tank Intact: Yes

Comments:

Bathroom have electrical fixtures. Just one toilet and one hand washer are manual in each bathroom.

Class Room Ventilation:

- Adequate Classroom Ventilation: Yes
- AC System Operating: No

Comments:

Access:

• Safe Access to Buildings: Yes

Comments:

Perimeter Fences/Walls:

• Damage to Perimeter or Fence: Minor/None

• Damage to Retaining Wall or Slope: Minor/None

Comments:

Perimeter fence damaged next to first grade classroom. Minor damage.

Overall Areas:

• Recreation Area Damage: Minor/None

• Parking Area Damage: Minor/None

• Falling Hazards in Play Areas: Minor/None

• Standing Water in Play Areas: Minor/None

• Debris or Tree Hazards: Minor/None

• Electrical or Power Line Hazards: Minor/None

Comments:

Lunch Room:

• Cooking Equipment: Yes

• Refrigerated or Dry Food Storage: Yes

• Operational Exhaust Fan: Yes

• Fire Suppression System: Yes

• Screens: Yes

Comments:

Buildings:

• Building 1: Green - Inspected

Comments:

Additional Comments:

Findings:

Broken window at first floor in first grade classroom and at second floor in math classroom; There is a moderated leak over the internet black box in second floor; Minor siding damage in bleachers.

Recommendations:

Broken windows opening need to be covered until can be repaired; Roof need to be sealed especially in the computer classroom area; Bleachers siding need to be replaced.