Facility Evaluation (Site) Form for: Jose Nevarez Lopez | Codigo: 71548

Inspector(s) Name: SJ-07 **Inspection Date:** Mon Oct 23 2017 **Inspection Time:** 10:30:13 GMT-0500 (Central Daylight Time) **Type of Facility:** comm_shelter **School Name:** Jose Nevarez Lopez **School Code:** 71548 Latitude: 18.40240305 Longitude: -66.25389775 **Building Contact:** Number of Buildings:

General:

- Facility Area Flooded: No
- One or More Buildings Flooded: No
- Other Water Damage in Facility: No

Comments:

Services:

- Potable Water Service: Yes
- Potable Water Cistern: Yes
- Sewer Service: No
- Septic Tank Available: Yes
- Electrical Power Service: No
- Generator Available: No
- Gas (LP) Storage Tank Intact: Yes

Comments:

The cisterns are connected to the lunch room.

Class Room Ventilation:

- Adequate Classroom Ventilation: Yes
- AC System Operating: No

Comments:

Access:

• Safe Access to Buildings: Yes

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: Minor/None
- Damage to Retaining Wall or Slope: Minor/None

Comments:

Some trees collapse on the back fence.

Overall Areas:

- Recreation Area Damage: Minor/None
- Parking Area Damage: Minor/None
- Falling Hazards in Play Areas: Minor/None
- Standing Water in Play Areas: Minor/None
- Debris or Tree Hazards: Minor/None
- Electrical or Power Line Hazards: Minor/None

Comments:

Lunch Room:

- Cooking Equipment: Yes
- Refrigerated or Dry Food Storage: Yes
- Operational Exhaust Fan: Yes
- Fire Suppression System: Yes
- Screens: Yes

Comments:

Buildings:

- Building 1: Green Inspected
- Building 2: Green Inspected
- Building 3: Green Inspected
- Building 4: Green Inspected

Comments:

They have the issue that the sentic tank need nower to operate. The basketball court lost some parts of the roof peeds to

mey note the issue that the separe tank need power to operate, the susketsan coart lost some parts of the root, needs to

be (close) barricaded. The school was used as shelter; now they don't have any refugee.

Additional Comments:

Findings:

1. Septic tank its not operate properly. 2. Basketball court lost some paneling in roof, and fence was damaged. 3. Water service is available.

Recommendations:

1. Septic tank needs power to operate properly. 2. Basketball court fix the perimeter fence and clean the debri material around. 3. Water service is available.