

Facility Evaluation (Site) Form for: Elem Bo Higuillar (Ecologica) | Codigo: 18259

Inspector(s) Name:

SJ-08

Inspection Date:

Mon Oct 23 2017

Inspection Time:

13:35:56 GMT-0500 (Central Daylight Time)

Type of Facility:

comm_shelter

School Name:

Elem Bo Higuillar (Ecologica)

School Code:

18259

Latitude:

18.43255338

Longitude:

-66.3012137

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

Comments:

Damages were minor, its a green building

Services:

- Potable Water Service: **No**
- Potable Water Cistern: **Yes**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **Yes**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Cistern requires electrical power, currently by generator

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

Comments:

N/A

Access:

- Safe Access to Buildings: **Yes**

Comments:

No

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Minor/None**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

N/A

Overall Areas:

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Minor/None**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

N/A

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **No**
- Screens: **Yes**

Comments:

Some windows screens damaged, roof skylight damaged.

Buildings:

- Building 1: **Green - Inspected**
- Building 2: **Green - Inspected**
- Building 3: **Green - Inspected**
- Building 4: **Green - Inspected**
- Building 5: **Green - Inspected**
- Building 6: **Green - Inspected**
- Building 7: **Green - Inspected**
- Building 8: **Green - Inspected**

Comments:

Minor roof water leaks. Only avfew windows need to be repaired. Only one jalousie damaged.

Additional Comments:

None

Findings:

1. Damaged fences 2. Minor roof water leakes 3. Roof skylight damaged 4. Ceiling mold 5. Several windows need to be repaired.

Recommendations:

1. Barricade fences until they can be repaired. 2. Repair roof. 3. Repair damaged skylight. 4. Restrict access where there is mold until it can be cleaned and disinfected. 5. Repaired damaged windows. 5. Replace missing skylight and 2 windows
