

# Facility Evaluation (Site) Form for: Alejandro Junior Cruz | Codigo: 71449

---

**Inspector(s) Name:**

Jonas Parker

**Inspection Date:**

Tue Oct 24 2017

**Inspection Time:**

12:42:17 GMT-0500 (Central Daylight Time)

**Type of Facility:**

comm\_shelter

**School Name:**

Alejandro Junior Cruz

**School Code:**

71449

**Latitude:**

18.3662612

**Longitude:**

-66.25668379

**Building Contact:****Number of Buildings:**

---

**General:**

- Facility Area Flooded: **No**
- One or More Buildings Flooded: **No**
- Other Water Damage in Facility: **No**

**Comments:**

---

**Services:**

- Potable Water Service: **Yes**
- Potable Water Cistern: **Yes**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **No**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

**Comments:**

No Water, no power. Cistern is just rain water, used by kitchen.

---

**Class Room Ventilation:**

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **No**

**Comments:**

1 ac unit damaged

---

**Access:**

- Safe Access to Buildings: **Yes**

**Comments:**

---

**Perimeter Fences/Walls:**

- Damage to Perimeter or Fence: **Moderate**
- Damage to Retaining Wall or Slope: **Minor/None**

**Comments:**

Fence collapsed along the rear

---

**Overall Areas:**

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Moderate**
- Electrical or Power Line Hazards: **Minor/None**

**Comments:**

Fallen tree until removed

---

**Lunch Room:**

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **No Data**
- Screens: **Unknown**

**Comments:**

---

**Buildings:**

- Building 1: **Green - Inspected**
- Building 2: **Yellow - Restricted Use**

**Comments:**

---

**Additional Comments:**

---

**Findings:**

1.No water service. 2.Perimeter fence damaged. 3.Presence of debris. 4.Severe filtration on lunch room storage. 5.Building 2, debris and fallen trees. 6.the pavillion is filled with pigeons,guano,standing water and mosquitos.

---

**Recommendations:**

1.fix perimeter fence or barricade the area 2.clean debri 3.roof treatment 4.pest control

---