# Facility Evaluation (Site) Form for: Maria C. Osorio | Codigo: 73890

Inspector(s) Name:
Jonas Parker
Inspection Date:
Wed Oct 25 2017
Inspection Time:
08:27:29 GMT-0500 (Central Daylight Time)
Type of Facility:
escuela
School Name:
Maria C. Osorio
School Code:
73890
Latitude:
18.36410306
Longitude:
-66.21197928
<b>Building Contact:</b>
Number of Buildings:

# **General:**

- Facility Area Flooded: Yes
- One or More Buildings Flooded: Yes
- Other Water Damage in Facility: Yes

#### **Comments:**

Flooding cleaned up. Minor leakage from roof damage

# **Services:**

Potable Water Service: YesPotable Water Cistern: No

• Sewer Service: No

Septic Tank Available: NoElectrical Power Service: No

• Generator Available: No

• Gas (LP) Storage Tank Intact: Yes

#### **Comments:**

No power

# **Class Room Ventilation:**

- Adequate Classroom Ventilation: Yes
- AC System Operating: No

#### **Comments:**

All ac condensers on roof damaged

# **Access:**

• Safe Access to Buildings: Yes

#### **Comments:**

# **Perimeter Fences/Walls:**

- Damage to Perimeter or Fence: Moderate
- Damage to Retaining Wall or Slope: Minor/None

#### **Comments:**

Fence w tree fall damage in a few places behind school and gate came off.

# **Overall Areas:**

- Recreation Area Damage: Minor/None
- Parking Area Damage: Minor/None
- Falling Hazards in Play Areas: Minor/None
- Standing Water in Play Areas: Minor/None
- Debris or Tree Hazards: Minor/None
- Electrical or Power Line Hazards: Minor/None

#### **Comments:**

# **Lunch Room:**

- Cooking Equipment: Yes
- Refrigerated or Dry Food Storage: Yes
- Operational Exhaust Fan: No
- Fire Suppression System: Yes
- Screens: No Data

# **Comments:**

Exhaust fan never worked

# **Buildings:**

- Building 1: Green Inspected
- Building 2: Green Inspected

• Building 3: Green - Inspected

# **Comments:**

# **Additional Comments:**

Fix some flashing. Clean gutters and drains so roofs don't leak. Fix entire ac system.

# **Findings:**

1.All the air conditioner system blew off/ broken. 2.A tree fall cause a minor leak. 3.Walkways broken. 4.Missing windows. 5.Minor leakage. 6.Flushing blew off the building. 7.Minor sagging of diagonal tension rod in the Basketball Court.

# **Recommendations:**

1.Drain the water from the roof. 2.Replace the windows. 3.Repair the walkway. 4.Repair the tension rod in the Basketball Court. or barricade until fix tension rod. 5.barricade perimeter fence area