

Hoja de Trámite

22 de enero de 2020

LL 40 011	010 40 2	JE O				
Para:	Dr. Eligi	mento de Educa o Hernández Pé rio de Educaciór	rez			
De:	Calle Pro	n Professional G ogreso # 50 – Su 7.918.5890 / 589	iite 202, Faja		roup	
Nombre	del Repre	esentante Autori	zado:	Manu	no Rere-	ι
			-irma:	1	-12	
Escuela:		JULIAN E BLANCO	(BALLET)	Codigo:	60	0038
Municipio):	SAN JUAN I	Fecha	Inspeccion: _	43	3841
	-	geniero que mendación:	EFREN RI	VERA	LIC:	8904
		De	ocumentos Er	atregados:		
			Journal 1103 Li	ili ogados.		
	1 2 3	Recomendacion Estampilla Dig Informe de ins	ital Especial	emitida por el C	CIAPR	

Entregado a:	The state of the s	Fecha:	1	23	2020	

G.	RECOMENDA	ACIÓN AL SECRETARIO		
	Departamento de Dr. Eligio Hernár Secretario de Ed	ndez Pérez	·	
	Hora de Entrada a Inspección:	8.30	F 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	0:30
	Escuela:	Julian E. Blanco	Código: 600	The state of the s
	Municipio:	Fan Juan	Fecha de Inspección:	11 Énero 2020
	Abrir Escuela (Ve Abrir Parcialmen No Abrir la Escue	ite la Escuela (Amarillo)		
	de S	Luego de rea ar de la escue San Juan mis a	Formen tavios	son 105
		1-No se iden VOSOBLE.	tofico din	2 estructual
				· · · · · · · · · · · · · · · · · · ·

			···· -··· · · · · · · · · · · · · · · ·	
			· · · · · · · · · · · · · · · · · · ·	WERA CARRES
		Rivera Carraquillo Molde) Cassapiillo	8904 #Licencia	LIGHTO RICO



COLEGIO DE INGENIEROS Y AGRIMENSORES DE PUERTO RICO

PO Box 363845 * San Juan, Puerto Rico * 00936-3845 Tel. 787-758-2250 * Fax. 787-758-7639

ESTAMPILLA DIGITAL ESPECIAL (EDE)

Ing. William Melendez Rivas, PE



Práctica de:

Ingeniería

Licencia:

16383

Renglón:

Certificación

Descripción del Trabajo: Trámites ante Entes Gubernamentales

Fecha de Emisión:

2020-01-21

Monto Emitido:

Número de Serie:

5967-7753-2160-5985

Número de Caso:

Código Escuela:60038

Proyecto / Unidad:

Escuela Julián E. Blanco, San Juan

Rol del Profesional:

Consultor



Certificación:

El profesional certifica con la emisión de la estampilla digital especial del Colegio de Ingenieros y Agrimensores de Puerto Rico el haber cumplido con las disposiciones de la Sección 11 de la Ley 319 del 15 de mayo de 1938, según enmendada.

La colocación del sello profesional constituye la cancelación de la estampilla digital especial

GENERAL EARTHQUAKE DAMAGE OCULAR INSPECTION CHECKLIST

Α.	GENERAL INFORMATION
1.	Street Address of the School:
:	School Name: State: Poerro Rico Zip: School Name: Julian E. Blanco
2.	
3.	Date of inspection: 11 enero 2020
4.	Inspector's Name: Efren Rivera
В.	BUILDING SITE INSPECTION
5.	Utility Service Safety:
detecte	TANT-Immediately following an earthquake, check the entire property, especially near appliances, for the smell of gas. If gas odor is d, turn off the gas at the meter where it enters the house. Locate and repair leaks before turning gas back on. If the gas odor persists a gas has been shut off, vacate the building and contact the gas utility company immediately.
	TANT-Before entering a damaged, vacant building verify that gas is off. Check the gas meter for damage and position of main gas ither a manual valve or a seismically-activated gas shut-off valve. Do not enter the building if gas odor is detected.
	a. Odor of natural gas leakage? YES NO b. Downed powerlines? YES NO
6.	Surrounding topography: (@checkone) Flat Gently sloping (easily walkable) Steeply sloping (difficult or impossible to walk in some areas)
7.	Building pad: (@check one) Flat Terraced or multilevel Gently sloping (less than 4-foot ground surface elevation difference across house) Steeply sloping (greater than 4-foot ground surface elevation difference across house)
8.	Geotechnical Issues: (If yes, provide description and photos) YES NO
	a. New cracks in the ground?
12	b. Signs of fresh cracking in or movement of hardscape?
	c. Signs of fresh cracking in or movement of retaining walls? d. Patterns of cracking that extend through the ground surface, hardscape, and improvements?
9	d. Patterns of cracking that extend through the ground surface, hardscape, and improvements?
	e. Evidence of sand boils or other fresh-appearing deposits of sand or mud?
	f. Unusual slumping, rising, or bulging of the ground surface?
	g. Evidence of rock falls or slope instability above site?
	h. Ground movement or wet areas indicating possible broken underground utility lines?
	i. Other phenomena (e.g., septic tanks surfacing, differential settlement, ground consolidation)?

GENERALIEARTHOUAKE DAMAGE OCULAR INSPECTION CHECKEST

В.	BUILDING SITE INSPECTION (continued)			YES	NO
9.	Evidence of earthquake-induced permanent ground defor property?	rmation i	n the immediate vicinity of the		
C.	GENERAL BUILDING INFORMATION				
10.	Safety Assessment Tag: (☑check one)	Green	een		a.
11.	a) Year of original construction (best estimate): b) Total square footage (best estimate): Have any repairs, modifications, or demolition been perfectly yes, describe	ormed si		YES	NO ,
13.	Building configuration: a. Single story b. Combination one and two story c. Full two story d. Three story e. Split level f. Typical g. Other, describe	16. 17.	Sill bolting: a. Structure bolted to foundate by the structure not bolted to foundate c. Don't know Roof configuration: a. Gable b. Hip c. Flat or very low slope		
14.	Exterior wall finish: a. Stucco b. Panel siding c. Metal siding d. Masonry veneer e. Other, describe coment pluster	18.	d. Shed e. Other, describe Roof covering: a. Asphaltic membrane b. Wood shingle or shake c. Concrete	8	
15.	Foundation configuration: a. Slab-on-grade b. Crawlspace without cripple walls c. Crawlspace with cripple walls d. Exposed piers or posts e. Typical f. Metal g. Other, describe		d. Metal e. Elastomeric f. Other, describe		

D.	EXTERIOR BUILDING INSPECTION			
19	. General: (if yes, provide description and photos)	YES	NO	N/A
	a. Collapse, partial collapse, or building off foundation?			
	b. Obvious lean in any story?			
20.	Exterior walls: (if yes, provide description and photos)	_		-
	a. Fresh cracking at corners of door and window openings?			L
	b. Fresh cracking at building corners?			
	c. Door or window openings racked out of square?			
	d. Broken glass in windows or doors?		7	
	e. Wall leaning?			
	f. Bulging or delamination of stucco?			
	g. Pattern of cracking that extends from the ground surface, through foundation, and wall?			
	h. Evidence of recent relative movement at mudsill line?			
	i At locations where the exterior stucco is continuous from the framing down over the			
	foundation, is there cracking of stucco along the mudsill level accompanied by indications			
	of permanent displacement (sliding) of the building relative to the foundation?			posturacy
	j. Collapse, partial collapse, or separation of masonry veneer?	Ш		
	k. Severe cracking, separations, or offsets at building irregularities?			
21.	Foundation: (if yes, provide description and photos)	_		
	a. Fresh cracking of exposed perimeter foundation?	L		
	b. Relative movement between slab and footing in "two-pour" slab-on-grade foundations?			
	c. Ask homeowner if any earthquake retrofits have been done to the home?		L	
	If Y describe:			
	d. If the answer to c is Y, were bolts added to connect the home to the foundation?			
	e. If the answer to c is Y, were plywood or sheathing added to any cripple walls under the home?			

GENERALEARTERIUAKEEDAMAGEROLUUARINGBEOHONEGHEOKESTRA

D.	EXTERIOR BUILDING INSPECTION (continued)			
	22. Kitchen Hook (if yes, provide description and photos)	YES	NO	N/A
	a. Present on external wall?			
	b. Present at internal location?			
	c. Collapse or partial collapse?			
	d. Visible damage or cracking?			
	e. Visible tilting or separation from building?			
	f. Shifted or loose and displaced			
	g. Deterioration or deformation			
23.	Roof: (If yes, provide description and photos)		_	
	a. Shifted or dislodged or concrete damage?			
	b. Impact damage to roof from falling object?			
	c. Displaced rooftop HVAC units?			
	d. Significantly sagging roof ridgelines?			
	e. Signs of movement between rafter tails and wall finishes at eaves?			
	f Buckled/dislodged flashing or tearing of roof membrane, roof/wall intersections in split			
	level buildings, additions, or other building irregularities?		_/	
	g. Tearing of roof membrane or deck waterproofing at re-entrant corners?			
	h. Toppling, shifting, or damage/leakage at refrigerant and electrical lines of rooftop		I	
	mechanical equipment?			/
	i. Shifting of or damage to solar panels?			

GENERAL EARTHQUAKE DAMAGE OCULAR INSPECTION CHECKLIST

D.	EXTERIOR BUILDING INSPECTION (continued)			
24.	Attached or abutting improvements: (if yes, provide description and photos)	YES	NO	N/A
	a. Collapse, partial collapse, or separation of attached porches, carports, Gazebos, or			V
	awnings?	_	_/	
	b. Evidence of recent settlement or displacement of exterior steps, patios,		V	
	or walkways relative to the building?			
	c. Signs of movement between building floor and/ or exterior hardscape or retaining	Ш		
	wall along the uphill side of hon steeply sloping sites?			
100	d. Toppling, shifting, or damage/leakage at refrigerant and electrical lines of	Ц		
	air conditioning condenser unit(s)?			
25.	Independent exterior improvements: (if yes, provide description and photos)	_	_/	ļ
=	a. Damaged detached gazebo?			
	b. Damage to fences / privacy walls?			
	c. Damage to retaining walls?			
	d. Damage to walkway?			
	e. Evidence of leakage from water supply lines?			
	f. Toppling, shifting, or damage/leakage at fuel connection of propane tanks?			
	g. Others damage	Ц		Ш
E.	INTERIOR INSPECTION			
26.	General information a. If interior access not possible, identify reason b. Typical wall and ceiling	a finish		
	a. If interior access not possible, identify reason b. Typical wall and ceiling i. Red tag i. Drywall	a musii		
	☐ ii. Hazardous materials ☐ ii. Plaster on gyps	sum lath		
	iii. Other hazardous condition, iii. Plaster on woo	d lath	Motor	
	describe iv. Other, describe	(Dirien)	17005161	
	iv. Other, describe			

E.	INTERIOR INSPECTION (continued)			
27.	Walls: (if yes, provide description and photos)	YES	NO	N/A
	a. Fresh cracking, buckling, spalling, or detachment of interior wall finish at corners of			
	door and window openings?		/	
	b. Fresh cracking of wall finishes at wall corners or wall/ceiling intersections?			
	c. Door or window openings racked out of square?			
	d. Wall leaning?			
	e. Pattern of cracking that extends from the floor slab through the wall?			
	f. Movement or sliding of walls relative to the floor?			
	g. Severe cracking, separations, or offsets at building irregularities?			
	h. Doors damaged, difficult to operate, or inoperable?			
	i. Windows damaged, difficult to operate, or inoperable?			
28.	Ceilings: (if yes, provide description and photos)		,	
	a. Collapse of ceiling finish?			
	b. Fresh cracking of ceiling finishes, especially at re-entrant corners; cracks along corner			
	bead at stairwell openings; cracking or tearing of finishes at ceiling/wall juncture; or multiple			
	"nail pops"?		/	
	c. Damage to ceiling finishes in vicinity of corridors or commons places?			
	d. Separations or cracks in ceiling finishes at split-levels, re-entrant corners,			
	additions, appendages, or other building discontinuities?			
	e. Water damage or evidence of recent leakage from plumbing lines or roofing?			
1				

INTERIOR INSPECTION (continued)			
Floors: (if yes, provide description and photos)	YES	NO	N/A
a. Evidence of recent sloping, sagging, settlement or displacement of floors?			
b. In slab-on-grade locations, fresh cracking of floor slab or floor finishes?			
c. Significant sagging or unusual bounciness of floors frames?			
d. Separations or cracks in floor finishes at split-levels, re-entrant corners, additions,		اثـًا	السسا
appendages, or other building discontinuities?	П		
e. Signs of movement between floor and exterior hardscape or retaining wall along		151	
the uphill side of homes on steeply sloping sites?	П		П
f. A pattern of fresh cracks, gaps, or joint separations in floor finishes?			
g. Impact damage to floor finishes from falling contents?	Ш		Ш
			 1
Mechanical systems: (if yes, provide description and photos)	`		Ш
a. Displaced connection of appliance flues connected to chimneys?	[Γ-1
b. Toppling, shifting, leakage from tank, leakage from water connections displaced flue		ك	ب
connection or damage/leakage at gas line or electrical connection of water heater?	 _		[]
c. Shifting, damage/leakage at gas line, flue connection, electrical connection, refrigerant line,			
and condensate drain connection of furnace or air conditioning fan-coil unit?	لسا		Ш
d. Damage to gas line of gas stoves or gas fueled clothes dryers?			П
e. Damage to toilets?		تا	LJ
f. Decreased or restricted water pressure at appliances, faucets, or toilets?	П		
g. Toppling or shifting of free-standing wood stove and/or flue?			
h. Toppling, shifting, damage/leakage at fuel connection of fuel oil tank?			<u> </u>
i. Other Damage in the dining room			
j. Damage near the gas tank			
	 Floors: (if yes, provide description and photos) a. Evidence of recent sloping, sagging, settlement or displacement of floors? b. In slab-on-grade locations, fresh cracking of floor slab or floor finishes? c. Significant sagging or unusual bounciness of floors frames? d. Separations or cracks in floor finishes at split-levels, re-entrant corners, additions, appendages, or other building discontinuities? e. Signs of movement between floor and exterior hardscape or retaining wall along the uphill side of homes on steeply sloping sites? f. A pattern of fresh cracks, gaps, or joint separations in floor finishes? g. Impact damage to floor finishes from falling contents? Mechanical systems: (if yes, provide description and photos) a. Displaced connection of appliance flues connected to chimneys? b. Toppling, shifting, leakage from tank, leakage from water connections displaced flue connection or damage/leakage at gas line or electrical connection of water heater? c. Shifting, damage/leakage at gas line, flue connection, electrical connection, refrigerant line, and condensate drain connection of furnace or air conditioning fan-coil unit? d. Damage to gas line of gas stoves or gas fueled clothes dryers? e. Damage to toilets? f. Decreased or restricted water pressure at appliances, faucets, or toilets? g. Toppling or shifting of free-standing wood stove and/or flue? h. Toppling, shifting, damage/leakage at fuel connection of fuel oil tank? i. Other Damage in the clining room 	Floors: (if yes, provide description and photos) a. Evidence of recent sloping, sagging, settlement or displacement of floors? b. In slab-on-grade locations, fresh cracking of floor slab or floor finishes? c. Significant sagging or unusual bounciness of floors frames? d. Separations or cracks in floor finishes at split-levels, re-entrant corners, additions, appendages, or other building discontinuities? e. Signs of movement between floor and exterior hardscape or retaining wall along the uphill side of homes on steeply sloping sites? f. A pattern of fresh cracks, gaps, or joint separations in floor finishes? g. Impact damage to floor finishes from falling contents? Mechanical systems: (if yes, provide description and photos) a. Displaced connection of appliance flues connected to chimneys? b. Toppling, shifting, leakage from tank, leakage from water connections displaced flue connection or damage/leakage at gas line or electrical connection of water heater? c. Shifting, damage/leakage at gas line, flue connection, electrical connection, refrigerant line, and condensate drain connection of furnace or air conditioning fan-coil unit? d. Damage to gas line of gas stoves or gas fueled clothes dryers? e. Damage to tollets? f. Decreased or restricted water pressure at appliances, faucets, or tollets? g. Toppling or shifting of free-standing wood stove and/or flue? h. Toppling, shifting, damage/leakage at fuel connection of fuel oil tank? i. Other Damage in the dining room	Floors: (if yes, provide description and photos) a. Evidence of recent sloping, sagging, settlement or displacement of floors? b. In slab-on-grade locations, fresh cracking of floor slab or floor finishes? c. Significant sagging or unusual bounciness of floors frames? d. Separations or cracks in floor finishes at split-levels, re-entrant corners, additions, appendages, or other building discontinuities? e. Signs of movement between floor and exterior hardscape or retaining wall along the uphill side of homes on steeply sloping sites? f. A pattern of fresh cracks, gaps, or joint separations in floor finishes? g. Impact damage to floor finishes from falling contents? Mechanical systems: (if yes, provide description and photos) a. Displaced connection of appliance flues connected to chimneys? b. Toppling, shifting, leakage from tank, leskage from water connections displaced flue connection or damage/leakage at gas line or electrical connection of water heater? c. Shifting, damage/leakage at gas line, flue connection, electrical connection, refrigerant line, and condensate drain connection of furnace or air conditioning fan-coil unit? d. Damage to gas line of gas stoves or gas fueled clothes dryers? e. Damage to toilets? f. Decreased or restricted water pressure at appliances, faucets, or toilets? g. Toppling or shifting of free-standing wood stove and/or flue? h. Toppling, shifting, damage/leakage at fuel connection of fuel oil tank? i. Other Damage in the dining room

E.	INTERIOR INSPECTION (continued)			
31.	Architectural woodwork and special finishes: (if yes, provide description and photos)	YES	NO	N/A
	a. Shifting of or damage to kitchen or bathroom cabinetry?			
	b. Impact damage to countertops from falling objects?			
	c. Cracking of ceramic tile in showers or tub/shower enclosures consistent with			
	earthquake damage to adjacent wall finishes?			
F.	CONTINGENT INSPECTIONS			
		YES	NO	N/A
32.	Retaining Tank Wall damage?			
33.	Water tank or other field subterranean structure			







