# Facility Evaluation (Site) Form for: Libre De Musica | Codigo: 14316

## Inspector(s) Name: SJ 14 **Inspection Date:** Mon Oct 23 2017 **Inspection Time:** 10:00:00 GMT-0500 (Central Daylight Time) Type of Facility: escuela **School Name:** Libre De Musica **School Code:** 14316 Latitude: 18.4413108 Longitude: -66.67060492 **Building Contact:**

## **General:**

• Facility Area Flooded: No

• One or More Buildings Flooded: No

• Other Water Damage in Facility: Yes

#### **Comments:**

**Number of Buildings:** 

Water Filtration inside Classrooms

### **Services:**

Potable Water Service: YesPotable Water Cistern: No

• Sewer Service: Yes

Septic Tank Available: NoElectrical Power Service: No

• Generator Available: No

• Gas (LP) Storage Tank Intact: No

#### **Comments:**

## **Class Room Ventilation:**

- Adequate Classroom Ventilation: Yes
- AC System Operating: No

#### **Comments:**

### **Access:**

• Safe Access to Buildings: Yes

#### **Comments:**

## **Perimeter Fences/Walls:**

- Damage to Perimeter or Fence: Minor/None
- Damage to Retaining Wall or Slope: Minor/None

#### **Comments:**

## **Overall Areas:**

- Recreation Area Damage: Minor/None
- Parking Area Damage: Minor/None
- Falling Hazards in Play Areas: Minor/None
- Standing Water in Play Areas: Minor/None
- Debris or Tree Hazards: Moderate
- Electrical or Power Line Hazards: Minor/None

#### **Comments:**

Tree debris and garbage at back side of school

## **Lunch Room:**

- Cooking Equipment: No
- Refrigerated or Dry Food Storage: No
- Operational Exhaust Fan: No
- Fire Suppression System: No
- Screens: No

## **Comments:**

Since this is a specialized school there is no lunch room.

## **Buildings:**

• Building 1: Yellow - Restricted Use

## **Comments:**

## **Additional Comments:**

## **Findings:**

1. Water leak problem inside classrooms due to clogged roof drains. 2. Collapse of ceiling elements in differents parts of the second floor. 3. Tree debris and garbage at back of the school.

## **Recommendations:**

1. Roof drain pipes must be cleared of debris. 2. Clean debris and garbage.