

Facility Evaluation (Site) Form for: Marta Velez De Fajardo |Codigo: 70250

Inspector(s) Name:

Ivelisse Ayala, , ,

Inspection Date:

Wed Oct 18 2017

Inspection Time:

05:00:00 GMT-0500 (Central Daylight Time)

Type of Facility:**School Name:**

Marta Velez De Fajardo

School Code:

70250

Latitude:

18.35195279

Longitude:

-66.18647591

Building Contact:**Number of Buildings:**

General:

- Facility Area Flooded: **Yes**
- One or More Buildings Flooded: **Yes**
- Other Water Damage in Facility: **Yes**

Comments:

Multiple buildings continue to flood during rain

Services:

- Potable Water Service: **Yes**
- Potable Water Cistern: **No**
- Sewer Service: **Yes**
- Septic Tank Available: **No**
- Electrical Power Service: **Yes**
- Generator Available: **No**
- Gas (LP) Storage Tank Intact: **Yes**

Comments:

Potable water: limited hours/low flow

Class Room Ventilation:

- Adequate Classroom Ventilation: **Yes**
- AC System Operating: **Yes**

Comments:

Access:

- Safe Access to Buildings: **Yes**

Comments:

Perimeter Fences/Walls:

- Damage to Perimeter or Fence: **Minor/None**
- Damage to Retaining Wall or Slope: **Minor/None**

Comments:

Overall Areas:

- Recreation Area Damage: **Minor/None**
- Parking Area Damage: **Minor/None**
- Falling Hazards in Play Areas: **Minor/None**
- Standing Water in Play Areas: **Minor/None**
- Debris or Tree Hazards: **Moderate**
- Electrical or Power Line Hazards: **Minor/None**

Comments:

Lunch Room:

- Cooking Equipment: **Yes**
- Refrigerated or Dry Food Storage: **Yes**
- Operational Exhaust Fan: **Yes**
- Fire Suppression System: **Yes**
- Screens: **Yes**

Comments:

Buildings:

Comments:

Additional Comments:

Findings:

1. Multiple buildings continue to flood when it rains. 2. Potable water service: limited hours and low water pressure 3. Debris in campus 4. Main Bldg: flooding damaged vinyl tile flooring; leaks through light fixtures; ceiling panels are sagging and may fall 5. Kindergarten Bldg: Fallen tree in roof corner; bearing wall is bent from an impact 6. Gym: damaged roof

Recommendations:

1. Verify drainage of flooded buildings. Barricade areas where flooding occurs until water is cleaned. 2. Barricade debris until they are removed. 3. Main Bldg: Restrict access to flooded classroom and remove ceiling panels. 4. Kindergarten Bldg: Barricade area around fallen tree until it can be removed. Barricade playground area where wall is bent until it can be repaired. 5. Gym: Barricade bleachers area and where metal roof panels are loose.
